

To test set the Command Source=Fieldbus and Op mode=Velocity for both axes using Workbench:



To demonstrate forcing was used. The user will want to write PLC code to control the drive as no AOI exists for this mode.

Using AXIS ONE as an example:

Per the instructions set byte 2 of the command assembly (output data) to 0x08.

Set bytes 12-15 to velocity setpoint data (i.e. in this case 0xA0000=655360 which equates to 10 rps or 600 rpm)

Name	Value	Force Mask	Style	Data Type	Description	Consta
AXIS_ONE.Output.Data		{...}	{...}	Decimal	Axis Data: Data to th...	
AXIS_ONE.Output.Data[0]	-119		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[1]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[2]	16#08		Hex	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[3]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[4]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[5]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[6]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[7]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[8]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[9]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[10]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[11]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[12]	16#00		Hex	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[13]	16#00		Hex	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[14]	16#0a		Hex	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[15]	16#00		Hex	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[16]	0		Decimal	SINT	Axis Data: Data to th...	
AXIS_ONE.Output.Data[17]	0		Decimal	SINT	Axis Data: Data to th...	

Note below the axis is already enabled (i.e. set by the AKD_Enable AOI).
 Set the Direction in the Control Word to 1 (positive) to demonstrate.

Name	Value	Force Mask	Style	Data Type	Description
AXIS_ONE		{...}	{...}	AKD_Axis	Axis Data:
AXIS_ONE.Control		{...}	{...}	AKD_Control	Axis Data: Control bi...
AXIS_ONE.Control.Load_Data_Start_Profile	0		Decimal	BOOL	Axis Data: Load Com...
AXIS_ONE.Control.Start_Block	0		Decimal	BOOL	Axis Data: Execute C...
AXIS_ONE.Control.Incremental	0		Decimal	BOOL	Axis Data: Increment...
AXIS_ONE.Control.Direction	1		Decimal	BOOL	Axis Data: Direction i...
AXIS_ONE.Control.Smooth_Stop	0		Decimal	BOOL	Axis Data: Smooth / ...
AXIS_ONE.Control.Hard_Stop	0		Decimal	BOOL	Axis Data: Hard / Im...
AXIS_ONE.Control.Reg_Arm	0		Decimal	BOOL	Axis Data: Arm the R...
AXIS_ONE.Control.Enable	1		Decimal	BOOL	Axis Data: Enable Ou...

Toggle the load/start bit from 0 to 1 to start rotation.

Name	Value	Force Mask	Style	Data Type	Description
AXIS_ONE		{...}	{...}	AKD_Axis	Axis Data:
AXIS_ONE.Control		{...}	{...}	AKD_Control	Axis Data: Control bi...
AXIS_ONE.Control.Load_Data_Start_Profile	1		Decimal	BOOL	Axis Data: Load Com...
AXIS_ONE.Control.Start_Block	0		Decimal	BOOL	Axis Data: Execute C...
AXIS_ONE.Control.Incremental	0		Decimal	BOOL	Axis Data: Increment...
AXIS_ONE.Control.Direction	1		Decimal	BOOL	Axis Data: Direction i...
AXIS_ONE.Control.Smooth_Stop	0		Decimal	BOOL	Axis Data: Smooth / ...
AXIS_ONE.Control.Hard_Stop	0		Decimal	BOOL	Axis Data: Hard / Im...
AXIS_ONE.Control.Reg_Arm	0		Decimal	BOOL	Axis Data: Arm the R...
AXIS_ONE.Control.Enable	1		Decimal	BOOL	Axis Data: Enable Ou...

From Workbench the motor is running 600 rpm (the units were set to rpm for demonstration).

AR Filter	PI Controller	Observer	Source	Status
Velocity Command:	600.000	rpm		
Velocity Feedback:	603.768	rpm		
Velocity Error:	-0.715	rpm		
Current Command:	0.050	Ams		

Without changing the control word the velocity setpoint data was changed from 0xA0000 to 0x10000 (1 rps or 60 rpm).

Name	Value	Force Mask	Style	Data Type	Description	Con
▶ AXIS_ONE.Output.Data[0]		-119	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[1]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[2]		16#08	Hex	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[3]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[4]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[5]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[6]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[7]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[8]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[9]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[10]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[11]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[12]		16#00	Hex	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[13]		16#00	Hex	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[14]		16#01	Hex	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[15]		16#00	Hex	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[16]		0	Decimal	SINT	Axis Data: Data to th...	
▶ AXIS_ONE.Output.Data[17]		0	Decimal	SINT	Axis Data: Data to th...	

From Workbench

AR Filter	PI Controller	Observer	Source	Status
Velocity Command:	<input type="text" value="60.000"/>			rpm
Velocity Feedback:	<input type="text" value="53.259"/>			rpm
Velocity Error:	<input type="text" value="11.284"/>			rpm
Current Command:	<input type="text" value="0.033"/>			Ams

With this setup it is also possible to change the Direction bit in the control word from 1 to 0 and the axis ran at -60rpm (on the fly).

Axis 2 works the same way.