


Superior Synchronous Connection Diagrams

SS240, SS450 Connection Diagrams


C Connection



DIRECTION OF ROTATION DETERMINED WHEN VIEWED FROM NAMEPLATE END OF MOTOR.

Single-Phase Operation

3 Ø Connection



DIRECTION OF ROTATION DETERMINED WHEN VIEWED FROM NAMEPLATE END OF MOTOR.

* — WHITE IS NOT "NEUTRAL".


Three-Phase Operation

Terminations

Lead Color	Terminal Box Motor
Red	Terminal # 1
Black	Terminal # 3
White	Terminal # 2

Hazardous Duty Motors Connection Diagrams

R/C Connection




NOTE:
1 - Direction or rotation is determined when viewed from end opposite mounting surface.

Single-Phase Operation

KS06, KS09, KS11 Series Connection Diagrams


R/C Connection



NOTE:
1 - Direction or rotation is determined when viewed from end opposite mounting surface.

Single-Phase Operation

R/R/C Connection



2 - Number in diagrams represent terminal connection when motors are supplied with terminal boards.

Single-Phase Operation